PRELIMINARY INSPECTION FOR YIO CHU KANG SECONDARY SCHOOL

3063 Ang Mo Kio Avenue 5,
Singapore 569868

(Preliminary Inspection Report)

Date: 17th December 2021

Time In: 08.40am Time Out: 09.20am

Service Report Series Number: 69426

Preliminary Inspection

An inspection was conducted on the 17th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: In between canteen staff entrance and rear gate





Findings & Recommendation:

1) Spotted uneven cracks and crevices can collect rain water that might become potential mosquitoes breeding.
2) Kindly seal up the cracks and crevices for preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69426

Name & Contact : Yio Chu Kang Secondary Date : 17/12/2021

Address : 3013, Ang Mo Kio Ave 5 Time in : 0840 hrs

Time out : 0920 hrs

PRELIMINARY REPORT

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☐ Spraying
☑ Cockroaches		☐ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☐ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☑ Others Please Specify: ALL PESTS		☐ Others Please Specify:

Remarks: Uneven cracks in stone path between canteen staff entrance & rear gate. Potential breeding ground for mosquito due to water seepage.

Observation / Recommendations : Advise to cover cracks to prevent seepage causing uneven stagnation.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Faiem / Hamid
Service Attended By

YIO CHU KANG SEC SCHOOL

TCH S1/AM
Client's Acknowledgement