PRELIMINARY INSPECTION FOR MAYFLOWER PRIMARY SCHOOL (HOLDING)

6 Ang Mo Kio Avenue 2,
Singapore 569948

(Preliminary Inspection Report)

Date: 16th December 2021

Time In: 10.00am Time Out: 11.00am

Service Report Series Number: 69155

Preliminary Inspection

An inspection was conducted on the 16th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Interceptor drain at walkway near to guardhouse






Findings & Recommendations:

1) Spotted stagnant water in the drain due to uneven drain gradient. No active mosquito larva was found during the time of inspection.
2) Advised to rectify the uneven gradient for preventive measures.

Location: Behind canteen near to fencing area



Findings & Recommendations:

1) Spotted uneven ground that might collect rain water and become potential mosquitoes breeding.
2) Advised to backfill the uneven ground for preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69155

Name & Contact : Mayflower Pri Sch

Date : 16/12/21

Address : 6 Ang Mo Kio Ave 7

Time in : 1000

Time out : 1100

Preliminary Report

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☐ Spraying
☑ Cockroaches		☐ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☐ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☑ Others Please Specify: All Pests		☐ Others Please Specify:

Remarks: Inspection for all pests at surrounding premise. Found 02 bald spots on grass patch at fencing behind canteen which can collect water during heavy rain. Found stagnant water in interceptor drain at walkway near guardhouse due to uneven gradient.

Observation / Recommendations : Advise to repair soil on bald patches and to even up drain at interceptor.

SOR : _____

☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Azahar
Service Attended By

MAYFLOWER PRIMARY SCHOOL
Client's Acknowledgement