PRELIMINARY INSPECTION FOR FORMER NORTH VIEW SECONDARY SCHOOL

530, Yishun Ring Road,

Singapore 768680

(Preliminary Inspection Report)

Date: 24th December 2021

Time In: 09.00am Time Out: 10.00am

Service Report Series Number: 69644

Preliminary Inspection

An inspection was conducted on the 24th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Near main gate



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: In front of the school along the drain



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Hand washing bay



Findings & Recommendation:

1) No active mosquito larva was found during the time of inspection. Besides, No water bearing receptacles was found within the premises. Kindly maintain well the entire vicinity for preventive measures.

Location: Back of the school drain





Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Canteen



Findings & Recommendation:

1) No active mosquito larva was found during the time of inspection of the gully trap. Kindly maintain well the entire vicinity for preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69644

Name & Contact : Guard Segar Date : 24/12/2021

Address : Former North View sec Sch Time in : 9.00 Am

Blk 360 Yishun Ring Rd. Time out : 10.00 Am

Preliminary Report for the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection done no activity found.	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☐ Bees	All Pest	☐ Traps
☐ Others Please Specify:	Watar Ponding near main Gate, along the drains infront of the	☐ Others Please Specify:

Remarks: School, near Washing bay Back of the School, Inside gardens all the drain, garle tirap at Canteen. Roof top Inspection done no activity found.

Observation / Recommendations: Advice to clear all chocked drain, to prevent against breeding and other pest.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Service Attended By

Client's Acknowledgement