PRELIMINARY INSPECTION FOR NORTHLAND PRIMARY SCHOOL

15 Yishun Avenue 4,
Singapore 769026

(Preliminary Inspection Report)

Date: 17th December 2021

Time In: 12.30pm Time Out: 13.20pm

Service Report Series Number: 69432

Preliminary Inspection

An inspection was conducted on the 17th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Fire hydrant FH4-4









Findings & Recommendation:

1) Spotted exposed PUB pit keyhole can collect rain water that might become potential mosquitoes breeding.
2) Kindly fill up the keyhole with sand particles for preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69432

Name & Contact : NORTHLAND PRIMARY SCHOOL Date : 17/12/2021

Address : 15, YISHUN AVE 4 Time in : 1230 hrs

Time out : 1320 hrs

(PRELIMINARY REPORT)

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☐ Spraying
☑ Cockroaches		☐ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☐ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☑ Others Please Specify: ALL PESTS		☐ Others Please Specify:

Remarks: PUB pit near hydrant FH4-4. Stagnant water inside due to uncovered keyhole. Potential mosquito breeding ground if left uncovered

Observation / Recommendations : Recommend to insert stopper or apply tape to prevent stagnation from taking place

SOR :

☐ Term Contract ☐ Ad-Hoc Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

FAIRUS / HAMID
Service Attended By

17/12/21
Client's Acknowledgement