PRELIMINARY INSPECTION FOR ANDERSON SERANGOON JUNIOR COLLEGE

4500 Ang Mo Kio Ave 6,
Singapore 569843

(Preliminary Inspection Report)

Date: 22nd December 2021

Time In: 09.00am Time Out: 10.00am

Service Report Series Number: 69614

Preliminary Inspection

An inspection was conducted on the 22nd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Near to gate 5



Findings & Recommendation:

1) Spotted suspected rodent activity and placed rodenticides bait for the control of rodents.
2) To be follow up closely during routine service.

Location: Near to rock climbing area



Findings & Recommendation:


1) Spotted suspected rodent activity and placed rodenticides bait for the control of rodents.
2) To be follow up closely during routine service.

Location: Teaching staff room 1224



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69614

Name & Contact : OM MR SAM Date : 22/12/2021

Address : Anderson Serangoon Junior College. H3O6 Ang Mo Kio Ave 6 Time in :

Time out :

Preliminery Report of the Math 12/21

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☒ Bees		☐ Traps
☐ Others Please Specify:	Water Ponding near GYM	☐ Others Please Specify:

Remarks: a bit boll has tide drain choked, near non-teaching staff room 12-24 drain not leval, near entrance auditium 12-17 ~~drin not leval, w/p near biology lab~~ 314 Walter chocked drain not Level, Rodent Baiting near Canten Stair case, found activity, Replace rodent's Cage. Inspection of rooftop no activity found.

Observation / Recommendations : Adviase to clear the choked drain to prevent aginst breeding, and other pest

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

MR SAM KWOK
Operations Manager
Anderson Serangoon Junior College

Service Attended By
Saiful

Client's Acknowledgement
Signature / Co Stamp

NEA Registration No. : NEA199707550Z