PRELIMINARY INSPECTION FOR WELLINGTON PRIMARY SCHOOL

10 Wellington Cir,

Singapore 757702

(Preliminary Inspection Report)

Date: 23rd December 2021

Time In: 09.00am Time Out: 10.00am

Service Report Series Number: 69624

Preliminary Inspection

An inspection was conducted on the 20th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Fencing at football field



Findings & Recommendation:

1) Spotted water ponding at the right side of drain.

Location: Meter Chamber



Findings & Recommendation:

1) Spotted water ponding at the meter chamber.

Location: Staircase 7 near to canteen



Findings & Recommendation:

1) Spotted water ponding at the on the ground.


Location: Mango Tree Garden



Findings & Recommendation:


1) Spotted suspected rodent burrow on the ground.
2) Placed rodenticides bait for the control of rodents.

Location: ISH 6th floor par room & 4th floor west wing



Findings & Recommendation:

1) Spotted drywood termites fecal accumulation on the flooring.
2) Treated the termites and to be monitor closely during the routine service.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69624

Name & Contact : OM MR. Keny Date : 23/12/2021

Address : Wellington Pri Sch Time in : 9.00 Am

10 Wellington Circle. Time out : 10.00 Am

Preliminary Report for the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites	Inspection	☑ Spraying
☑ Cockroaches		☑ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)	Inspection	☑ Baiting
☑ Mosquitoes		☐ Dusting
☐ Bees		☐ Traps
☐ Others Please Specify:	All Pest	☐ Others Please Specify:

Remarks: Water Ponding at the field right Side drain with dry leaves, w/p at water meter clamper w/p near Canteen and staircase 7. Rodent's Baiting near Mango tree, garden and canteen song of Indra tree. Termites inspection at 1SH 6th floor, Par room and 4th floor West Wing found dry wood termites, Treatment done at 4th floor West wing only.

Observation / Recommendations : Advice: To clear the chocked drains to prevent aginst breeding and other Pest.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

WELLINGTON PRIMARY SCH