PRELIMINARY INSPECTION FOR SERANGOON GARDEN SECONDARY SCHOOL

21 Serangoon North Avenue 1,
Singapore 555889

(Preliminary Inspection Report)

Date: 17th December 2021

Time In: 13.00pm Time Out: 13.50pm

Service Report Series Number: 69171


Preliminary Inspection

An inspection was conducted on the 17th December 2021 at the above school. In summary, found active termites activity at level 1 electrical riser besides staircase 8, termite baiting has been placed and to be follow-up closely during routine service.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Display Shelter





Findings & Recommendation:

1) Spotted old termites trails on the shelf surface with no active termites activity during the time of inspection.

Location: Electrical riser near SC 8







Findings & Recommendation:

1) Spotted active termites activity on the door frames and termite baiting has been placed for the control of termites' colony.
2) To be follow-up closely during routine service.

Location: Field facing HDB









Findings & Recommendation:

1) Spotted few rodents burrows at the football field that facing HDB estate.
2) Carried out rodenticide baiting into the burrows and to be follow-up closely during the routine service.

Location: Field landscape







Findings & Recommendation:

1) Spotted some discarded items on the ground that might become potential mosquitoes breeding.
2) Kindly maintain good housekeeping and clean up the discarded items for preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69171

Name & Contact : Serangoon Garden Sec

Address : 21 Serangoon North Ave 1

Date : 17/12/21

Time in : 1300

Time out : 1350

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☐ Spraying
☑ Cockroaches		☐ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☐ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☑ Others Please Specify: All pests		☐ Others Please Specify:

Remarks: Inspection for all pests at surrounding premise. Found rodent burrows at football field facing HDB. Found all burrows to be inactive as baits not consumed. Found food debris at field area. On going active termite baiting treatment at Electrical riser at level 1 beside staircase 8. Found old termite trace in display cabinet outside G.O with no termite activities. Advise to cover up burrows at field and to clear up rubbish at football field

Observation / Recommendations :

SOR :

☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Azahar

Service Attended By

Client's Acknowledgement