PRELIMINARY INSPECTION FOR NORTHBROOKS SECONDARY SCHOOL

585 Yishun Ring Rd,

Singapore 768692

(Preliminary Inspection Report)

Date: 23rd December 2021

Time In: 02.00pm Time Out: 03.00pm

Service Report Series Number: 69630

Preliminary Inspection

An inspection was conducted on the 23rd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Fencing at football field



Findings & Recommendation:


1) Spotted water ponding that might become potential mosquitoes breeding. No active larva was found during the inspection.

Location: Near garden area



Findings & Recommendation:

1) Spotted water ponding that might become potential mosquitoes breeding. No active larva was found during the inspection.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69630

Name & Contact : OM MR. Hamran Date : 23/12/2021

Address : Northbrooks Sec Sch Time in : 2-02pm

585 Yishun Ring Rd. Time out : 3-00pm

Preliminary Report for the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☒ Bees	All Pest	☐ Traps
☐ Others Please Specify:		☐ Others Please Specify:

Remarks: Wattled Ponding near car park, Seawage Cover near Canteen, back of the School near Lay room 4/F1-07 chairs, table near garden, near bomb shelter drain, near hangar @ NBBS drain, near fire-engine parking lot and near chemistry laboratory 2. Rodents Inspection done, Termite and Roof top done, NO activity found

Observation / Recommendations : Advice to Clear all the Chocked drains to prevent against breeding and other pest.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Mr Hamran Bin Mohd Zain