Pest Control Service Report Summary

Messr	**OM - Ng Tee Tee**	**Service Sheet No.**	**46224**
Area		**Date**	**2022-06-24**
Periodic Task		**Time In**	**11:11**
		Time Out	**12:22**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		


PEST TYPE			
☑ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☑ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location

☑ Park View Primary School

Images






Remarks **found some containers at the garden. holding water. pls ask gardener to check every morning to pour away collected water. Place spar bag into drains/ rooftop where slow moving water n stagnant water was detected.**

Name Of Technician **Team member A1**

Customer Signature

Technician Signature