# PRELIMINARY INSPECTION FOR CHRIST CHURCH SECONDARY SCHOOL

20 Woodlands Dr 17,

Singapore 737924

(Preliminary Inspection Report)

**Date:** 17th December 2021

**Time In:** 10.20am Time Out: 11.00am

**Service Report Series Number:** 69346

## Preliminary Inspection

An inspection was conducted on the 17th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Parking lot Nos 14 till Bin Centre











**Findings & Recommendation:**

1) Spotted chocked drains with accumulation of water and fallen dried leaves that might become potential mosquitoes breeding.
2) Kindly maintain well the housekeeping and clean up the fallen dried leaves for preventive measures.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

**Pest Control Service Report** S/NO: 69346

Name & Contact : Christ Church Secondary School Date : 17/12/21

Address : 20 Woodlands Drive 17 Time in : 1020

Time out : 1100

Preliminary Report

| Pest Contracted | Infestation / Service Location | Type Of Treatment |
|---|---|---|
| ☑ Subterranean Termites | | ☐ Spraying |
| ☑ Cockroaches | | ☐ Larviciding |
| ☑ Ants (Common / Red) | | ☐ Fogging |
| ☑ Rodents ( Rats / Mice) | | ☐ Baiting |
| ☑ Mosquitoes | | ☐ Dusting |
| ☑ Bees | | ☐ Traps |
| ☑ Others Please Specify: All Pest | | ☐ Others Please Specify: |

Remarks: Carried out all Pest inspection. found choked drains at parking lot 14 till bin centre, advice to clear. found no sign of other pest upon time of service.

Observation / Recommendations :

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Hairi / Shahron

CHRIST CHURCH SECONDARY SCHOOL

Eric Tan 17/12/21