PRELIMINARY INSPECTION FOR ANG MO KIO SECONDARY SCHOOL

6 Ang Mo Kio Street 22,
Singapore 569362

(Preliminary Inspection Report)

Date: 16th December 2021

Time In: 15.00pm Time Out: 16.10pm

Service Report Series Number: 69163

Preliminary Inspection

An inspection was conducted on the 16th December 2021 at the above school. In summary, found active rodent burrows at fencing behind carpark lot Nos 1.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Car park lot No. 1









Findings & Recommendations:

1) Spotted few rodents burrow at car park lot no. 1 on landscape area during the time of inspection. Placed rodenticides bait inside the burrows for monitoring
2) Advised to backfill the burrow once inactive for preventive measures.

Location: Fencing at field drain









Findings & Recommendations:

1) Spotted plants growing and soil deposit inside the drains which disrupt water flow that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clear the plants and clean the drain for preventive measure.

Location: Near shelter walkway










Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3132
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69163

Name & Contact : Ang Mo Kio Sec Sch Date : 16/12/21

Address : 6 Ang Mo Kio St 22 Time In : 1500

Time out : 1610

Preliminary Report

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites		☐ Spraying
☒ Cockroaches		☐ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)		☐ Baiting
☒ Mosquitoes		☐ Dusting
☒ Bees		☐ Traps
☒ Others Please Specify: All pests		☐ Others Please Specify:

Remarks: Inspection for all pests at surrounding premise. Found active rodent burrows at fencing behind Carpark Lot No. 1. Ongoing treatment with tied up rodent baits. Found choked drains due to accumulation of sands, black grains and plants at football fields and behind MCO office.

Observation / Recommendations : Advise to clear the above mentioned drains from plants, sands and blockages to enable water to flow smoothly without any blockage. To clear up burrows once treatment is done.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Azahar

Service Attended By

Client's Acknowledgement