PRELIMINARY INSPECTION FOR YISHUN PRIMARY SCHOOL

500 Yishun Ring Rd,

Singapore 768679

(Preliminary Inspection Report)

Date: 24th December 2021

Time In: 09.00am Time Out: 10.00am

Service Report Series Number: 69642

Preliminary Inspection

An inspection was conducted on the 24th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Near Lan riser C1-05



Findings & Recommendation:

1) Spotted water ponding at the canvas that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep the canvas clean and dry for preventive measure.

Location: Field gate C breaching inlet 6-11





Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Learning support coordinators room E1-01







Findings & Recommendation:


1) Spotted stagnant water at the flower pot that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep good housekeeping on regular basis for preventive measures.

Location: Near Bin centre



Findings & Recommendation:

1) Spotted opening that might become potential rodents harbourage area.
2) Placed rodenticides bait inside the burrows for monitoring and preventive measures.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69642

Name & Contact : OM MR. Saravanan Date : 24/12/2021

Address : Yishun Pri Sch Time in : 9.00 pm

500 Yishun Ring Rd Time out : 10.00 Am

Preliminary Report for the month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection done	☒ Spraying
☒ Cockroaches	no activity found	☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☐ Bees	All Pest	☐ Traps
☐ Others Please Specify:	Watter pooling near Lau riser C1-05, near field	☐ Others Please Specify:

Remarks: Gate 1, gate C breaching inlet 6-11, Learning Support Coordinator room E1-01, Fish pond in flower pots, Rodents Baiting near Bin Centr and garden no activity found, Roof top done, Termites Inspection done no activity found.

Observation / Recommendations : Advice to clean all the drains chocked with Mud & dried leaves to prevent beering and other pest.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow Up Service ☐ Re-Infestation Call Back

YISHUN PRIMARY SCHOOL SINGAPORE

Service Attended By Client's Acknowledgement