PRELIMINARY INSPECTION FOR NAVAL BASE SECONDARY SCHOOL

901 Yishun Ring Rd,
Singapore 768689

(Preliminary Inspection Report)

Date: 24th December 2021

Time In: 10.00am Time Out: 11.00am

Service Report Series Number: 69640

Preliminary Inspection

An inspection was conducted on the 24th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Canteen area



Findings & Recommendation:

1) Spotted suspected rodent activity and placed rodenticides bait for the control of rodents.
2) To be follow up closely during routine service.

Location: water meter chamber



Findings & Recommendation:


1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Breaching inlet 8-13



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69640

Name & Contact : ON MR. BALA

Date : 24/12/2021

Address : Naval Base Sec Sch

Time in : 10.00 Am

901, Yishun Ring Rd.

Time out : 11.00Am

Preliminary Report For the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection no activity found	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☐ Bees	All Pest	☐ Traps
☐ Others Please Specify: breaching	Water Ponding near Inlet 8-13, in a Plastic	☐ Others Please Specify:

Remarks: bag in bush near NBSS logo at Field, Field toilet Bowl must close and the drain along the right side of the School Compound Water Ponding near fish Pond drain, Rodent's Baiting and Roof top Inspection done.

Observation / Recommendations : Advice to clear the drains to avoid breeding and other Pest.

SOR :

☐ Term Contract ☐ Follow-Up Service

☐ Ad-Hoc / Single Service ☐ Re-Infestation Call Back

Service Attended By

Client's Acknowledgement Signature / Co Stamp