Pest Control Service Report Summary

Messr	**S/R Woodlands Secondary School**	**Service Sheet No.**	**88042**
Area		**Date**	**2022-06-03**
Periodic Task		**Time In**	**13:05**
		Time Out	**13:55**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☑ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding, Abate

Location
☑ Woodlands Secondary School

Images

			
Notes:	Notes:	Notes:	

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding and Abate granules applied to surrounding perimeter drains and internal garden areas for prevention of mosquito breeding.
Recommend to upkeep housekeeping especially at garden area behind power station,look out for upright unused pails to prevent water collection from rain.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Woodlands Secondary School**	**Service Sheet No.**	**90865**
Area		**Date**	**2022-06-07**
Periodic Task		**Time In**	**14:10**
		Time Out	**14:55**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Woodlands Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



Pest Control Service Report Summary

Messr	**Service Report Woodlands Secondary School**	**Service Sheet No.**	**93654**
Area		**Date**	**2022-06-10**
Periodic Task		**Time In**	**07:45**
		Time Out	**08:16**


TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location
☑ Woodlands Secondary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried out for Treatment and Inspection was done at the above mentioned. Location found breeding at the side of indoor basketball court close perimeter drains**

Name Of Technician **Abdullah Bin Md Kassim**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**Service Report Woodlands Secondary School**	**Service Sheet No.**	**96507**
Area		**Date**	**2022-06-14**
Periodic Task		**Time In**	**13:00**
		Time Out	**13:45**


TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			


OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location
☑ Woodlands Secondary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out treatment and inspection at the above address . Treatment was done at the surrounding perimeter drain of the school . As picture mention below at Checkpoint 11 as we aready inform the OM regarding potential area for mosquitoes to breed . Please do a follow up to clear up the sand gradient as it choke the drain**

Name Of Technician **Abdullah Bin Md Kassim**

Customer Signature **Technician Signature**

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Woodlands Secondary School**	**Service Sheet No.**	**98643**
Area		**Date**	**2022-06-17**
Periodic Task		**Time In**	**14:55**
		Time Out	**15:40**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Woodlands Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**S/R Woodlands Secondary School**	**Service Sheet No.**	**100682**
Area		**Date**	**2022-06-21**
Periodic Task		**Time In**	**15:20**
		Time Out	**16:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Woodlands Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding carried out to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



Pest Control Service Report Summary

Messr	**S/R Woodlands Secondary School**	**Service Sheet No.**	**102825**
Area		**Date**	**2022-06-24**
Periodic Task		**Time In**	**13:30**
		Time Out	**14:15**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Woodlands Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding carried out to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



Pest Control Service Report Summary

Messr	**Service Report Woodlands Secondary School**	**Service Sheet No.**	**103919**
Area		**Date**	**2022-06-28**
Periodic Task		**Time In**	**14:00**
		Time Out	**14:30**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location
☑ Woodlands Secondary School

Images

Remarks **Carried out treatment and inspection at the above mention . Larviciding was done at the surrounding perimeter drain of the school . At the point of service no pest activity were to be found .**

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**