PRELIMINARY INSPECTION FOR AHMAD IBRAHIM PRIMARY SCHOOL

10 Yishun Street 11,

Singapore 768643

(Preliminary Inspection Report)

Date: 23rd December 2021

Time In: 01.00pm Time Out: 02.00pm

Service Report Series Number: 69626

Preliminary Inspection

An inspection was conducted on the 23rd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:


Location: Side entrance area



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Canteen garden



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Canteen area



Findings & Recommendation:

1) Spotted suspected rodent activity and placed rodenticides bait for the control of rodents.
2) To be follow up closely during routine service.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69626

Name & Contact : OM MR Nadarajah Date : 23/12/2021

Address : Ahmad Ibrahim Prisch Time in : 1.00pm

10, Yishun St 11 Time out : 2.00pm

Preliminary Report for the month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☑ Spraying
☑ Cockroaches		☑ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☑ Baiting
☑ Mosquitoes		☐ Dusting
☐ Bees		☐ Traps
☐ Others Please Specify:	All Pest	☐ Others Please Specify:

Wathe Ponding at right side of the Entrance

Remarks: drain uneven, w/p behind of the school drain choke with mud, at the field left side drain choke with dry leaves. Rodents Baiting at Canteen and canteen garden for Inspection. Termites and Roof top done, no activity found.

Observation / Recommendations : Advice to clear the dried leaves and choked drains for preventive against breeding and other pest.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back