Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**152670**
Area		**Date**	**2022-12-01**
Periodic Task		**Time In**	**13:35**
		Time Out	**14:20**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larvaciding

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No pest or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature



Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**153746**
Area		**Date**	**2022-12-05**
Periodic Task		**Time In**	**14:05**
		Time Out	**14:45**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larvaciding

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done in door at the above mentioned location.No termite or mosquito activity found at the time of service.Service done indoor due to heavy rain.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**154831**
Area		**Date**	**2022-12-08**
Periodic Task		**Time In**	**13:50**
		Time Out	**14:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larvaciding

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.Ni termite or mosquito activity found at the time of service.Service done indoor due to lightning.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**155912**
Area		**Date**	**2022-12-12**
Periodic Task		**Time In**	**15:25**
		Time Out	**16:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation s & d

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**156988**
Area		**Date**	**2022-12-15**
Periodic Task		**Time In**	**13:45**
		Time Out	**14:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation s & d

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No termite or mosquito activity found at the time of service.**

Name Of Customer	**Ms Mechiele**	**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	





Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**158069**
Area		**Date**	**2022-12-19**
Periodic Task		**Time In**	**14:16**
		Time Out	**15:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larvaciding

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No mosquito activity found at the time of service.**

Name Of Customer	**Ms Asiah**	**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	





ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**159148**
Area		**Date**	**2022-12-22**
Periodic Task		**Time In**	**14:20**
		Time Out	**15:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larvaciding

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No pest or mosquito activity found at the time of service.**

Name Of Customer	**Ms Cindy**	**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	





Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**160255**
Area		**Date**	**2022-12-27**
Periodic Task		**Time In**	**14:25**
		Time Out	**15:15**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation s & d

Location
☑ Si Ling Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No mosquito activity found at the time of service.**

Name Of Customer	**Mdm Paramesh**	**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	





Pest Control Service Report Summary

Messr	**Si Ling Pri Sch**	**Service Sheet No.**	**161323**
Area		**Date**	**2022-12-29**
Periodic Task		**Time In**	**14:10**
		Time Out	**15:08**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation s & d and baiting

Location

☑ Si Ling Primary School

Images




Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Inspection and treatment done at the above mentioned location.No mosquito activity found at the time of service.Ref to PAL room 4th floor found active termite and trail in the electrical riser floor.Installed termite baiting station to trap the termite.Follow up next 14 days.**

Name Of Customer	**Ms Paramesh**	**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	



