PRELIMINARY INSPECTION FOR JIEMEN PRIMARY SCHOOL

2 Yishun Street 71,

Singapore 768515

(Preliminary Inspection Report)

Date: 24th December 2021

Time In: 09.00am Time Out: 10.00am

Service Report Series Number: 69639

Preliminary Inspection

An inspection was conducted on the 24th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:


Location: Near bicycle parking garage



Findings & Recommendation:

1) Spotted stagnant water that might become potential mosquitoes breeding.
2) Kindly maintain well the drains for preventive measures.

Location: Near fish pond



Findings & Recommendation:

1) Spotted stagnant water that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep good housekeeping on a regular basis for preventive measure.


Location: Near guard room



Findings & Recommendation:


1) Spotted stagnant water at the tree hole that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep good housekeeping on a regular basis for preventive measure.

Location: Near art room



Findings & Recommendation:

1) No active mosquito larva was found during the time of inspection. Besides, No water bearing receptacles was found within the premises.
2) Kindly maintain well the entire vicinity for preventive measures.



ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69639

Name & Contact : OM MR. Chu Date : 24/12/2021

Address : Jiemin Pri Sch Time in : 9.00 Am

2, Yishun St 71 Time out : 10.00 Am

Prieliminary Report for the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites	Inspection	☑ Spraying
☑ Cockroaches		☑ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)	Inspection	☑ Baiting
☑ Mosquitoes		☐ Dusting
☐ Bees		☐ Traps
☐ Others Please Specify:	All Pest.	☐ Others Please Specify:

Remarks: Water Ponding near cycle parking Garage, W/P near Fish Pond, W/P near art ROOM and Bambu tree hole near the Guard Service Place. Termites Inspetion done, Baitily for Rodent's done, Root top done No activity found at the time of Service.

Observation / Recommendations : Advice to clear all water Ponding to prevent against breeding and other pest

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

JIEMIN PRIMARY SCHOOL dP

Choo Ching Hai
Operations Manager
Jiemin Primary School

Service Attended By