ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**134154**
Area		**Date**	**2022-10-03**
Periodic Task		**Time In**	**07:45**
		Time Out	**08:25**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding carried out to canteen floor traps,and surrounding ground level service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature

Technician Signature



Pest Control Service Report Summary

Messr	**Ahmad Ibrahim Sec Sch Service Report**	**Service Sheet No.**	**135262**
Area		**Date**	**2022-10-06**
Periodic Task		**Time In**	**14:30**
		Time Out	**15:00**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Carried out inspection and larviciding at the above mention . Larviciding was done at the surrounding internal and external area of the school . At the point of service no pest / mosquitoe activity were to be found**

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature

Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**136349**
Area		**Date**	**2022-10-10**
Periodic Task		**Time In**	**14:10**
		Time Out	**15:00**




TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate, Ant Gel

Location
☑ Ahmad Ibrahim Secondary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks

Inspection carried out to the above mentioned location.
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
Attended ants feedback for Block E classroom 01-04..Light ants activities detected at window area..Gel treatment carried out..Will monitor and follow up during next routine service
No signs of active termites detected during time of inspection.

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**137432**
Area		**Date**	**2022-10-13**
Periodic Task		**Time In**	**14:20**
		Time Out	**15:20**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			


OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding.

Location
☑ Ahmad Ibrahim Secondary School


Images



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Inspection carried out to the above mentioned location.** **Larvaciding carried out to canteen floor traps,and surrounding ground level service and perimeter drains for prevention of mosquito breeding.** **Attended feedback for adult mosquito sightings at level 2 study corner..Aerosol treatment carried out to whole area for deterrence purposes** **No signs of active termites detected during time of inspection.**

Name Of Customer **Name Of Technician** **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**138513**
Area		**Date**	**2022-10-17**
Periodic Task		**Time In**	**13:15**
		Time Out	**13:55**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☑ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding carried out to canteen floor traps,and surrounding ground level service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**139599**
Area		**Date**	**2022-10-20**
Periodic Task		**Time In**	**13:15**
		Time Out	**14:00**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**140720**
Area		**Date**	**2022-10-25**
Periodic Task		**Time In**	**12:40**
		Time Out	**13:25**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.Larvaciding carried out to canteen floor traps,and surrounding ground level service and perimeter drains for prevention of mosquito breeding.No signs of active termites detected during time of inspection.**

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**141779**
Area		**Date**	**2022-10-27**
Periodic Task		**Time In**	**14:30**
		Time Out	**15:20**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☑ Other Pest(add name) Drywood Termites			


OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate, Dusting

Location
☑ Ahmad Ibrahim Secondary School

Images



Notes:



Notes:

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
Drywood termites activities detected at Level 4,Science Lab 2..Dusting treatment carried out accordingly,will monitor and follow up during next service.

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R Ahmad Ibrahim Secondary School**	**Service Sheet No.**	**142873**
Area		**Date**	**2022-10-31**
Periodic Task		**Time In**	**14:45**
		Time Out	**15:30**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Ahmad Ibrahim Secondary School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Customer

Customer Signature

Name Of Technician **Faizad Bin Shamsudin**

Technician Signature

