PRELIMINARY INSPECTION FOR NORTHLAND SECONDARY SCHOOL

3 Yishun Street 22,

Singapore 768578

(Preliminary Inspection Report)

Date: 23rd December 2021

Time In: 08.00am Time Out: 09.00am


Service Report Series Number: 69620

Preliminary Inspection

An inspection was conducted on the 23rd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:


Location: Co axil distribution room area



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Building N 2935-01



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Building N 2935-01



Findings & Recommendation:

1. Spotted suspected rodent burrow and placed rodenticides bait for the control of rodents.
2. To be follow up closely during routine service.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803

Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69620

Name & Contact : OM M's Cathrin

Date : 23 / 12 / 2021

Address : Northland Sec Sch

Time in : 8-00 Am

3, Yishun St 22

Time out : 9-00 Am

Priliminery Report of the Month 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☐ Bees		☐ Traps
☐ Others Please Specify:		☐ Others Please Specify:

Remarks: All Pest

Water Pooling at Sub Station, W/P near co-Axil distribution room and near ~~Pwd~~ Pwd/bldg # 2935-01. Rodents Baiting near dat store.

Observation / Recommendations : ~~Advice~~ to clear the chocked drains to preventing against breeding and other pest.

SOR :

☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

NORTHLAND SECONDARY SCHOOL

Service Attended By