Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**124429**
Area		**Date**	**2022-09-01**
Periodic Task		**Time In**	**08:30**
		Time Out	**09:15**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation GP/S&D

Location
☑ Fuchun Secondary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**
(Follow up Drywood Termite: Still got sign of drywood twrmite activity. Treatment done. follow up on next Thursday routine)

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature

Technician Signature

Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**125536**
Area		**Date**	**2022-09-05**
Periodic Task		**Time In**	**15:20**
		Time Out	**16:03**




TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&DLavarciding

Location
☑ Fuchun Secondary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection. (Raining drizzling)**

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**126589**
Area		**Date**	**2022-09-08**
Periodic Task		**Time In**	**08:15**
		Time Out	**08:55**


TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			


OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D

Location
☑ Fuchun Secondary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature

Technician Signature

Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**127720**
Area		**Date**	**2022-09-13**
Periodic Task		**Time In**	**08:00**
		Time Out	**08:45**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☑ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D

Location

☑ Fuchun Secondary School


Images



Notes:




Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out inspection, treatment, search and destroy @ internal school due to heavy rain. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**

Ants: Ants & Ants nest at Level 2 staircase 4 Destroy.
Rodent: No Rodent was found at cage n glueboard round the school.
Drywood Termite: Near GO. There still sign of activity found. Treatment done.

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**128750**
Area		**Date**	**2022-09-15**
Periodic Task		**Time In**	**08:35**
		Time Out	**09:20**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&Lavarciding

Location

☑ Fuchun Secondary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**

Photo 1. Found ants on wall behind blk B. Treatment done.
Photo 2,3&4 MOSQ Breeding found at Drain in front of bin centre. Treatment done. Due to drain choke with dry leaves and sant.

Feedback: Uneven gradient in drain need to be improvised for better smooth of water flowing.

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**SR: Fuchun Secondary School**	**Service Sheet No.**	**129854**
Area		**Date**	**2022-09-19**
Periodic Task		**Time In**	**13:25**
		Time Out	**14:00**


TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation GP/S&D

Location
☑ Fuchun Secondary School

Images




Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**

Ants at Bin centre and Blk B near D&T.

Uneven gradient in drain need to be improvised for better smooth of water flowing.

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Fuchun Secondary School**	**Service Sheet No.**	**130911**
Area		**Date**	**2022-09-22**
Periodic Task		**Time In**	**08:30**
		Time Out	**09:15**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation larviciding

Location
☑ Fuchun Secondary School

Images

Remarks **Inspection for termites and mosquitoes at surrounding areas. No mosquitoes or termites activity found at time of inspection. Larviciding done at surrounding drains and other potential areas for prevention against mosquitoes.**

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**SR: Fuchun Secondary School**	**Service Sheet No.**	**132024**
Area		**Date**	**2022-09-26**
Periodic Task		**Time In**	**14:50**
		Time Out	**15:25**





TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D

Location
☑ Fuchun Secondary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite & MOSQ breeding was observed during the time of inspection.**

Feedback: Uneven gradient in drain need to be improvised for better smooth of water flowing.

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**SR: Fuchun Secondary School**	**Service Sheet No.**	**133663**
Area		**Date**	**2022-09-30**
Periodic Task		**Time In**	**07:50**
		Time Out	**08:35**


TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D

Location
☑ Fuchun Secondary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried out inspection, treatment, search and destroy @ entire school. No sign of s/termite was observed during the time of inspection.**
Found ants @ visitors wating area. treatment done.
Found first and Second stage MOSQ breeding at level 3 water pump tank. Destroy all breeding.

Name Of Technician **Muhammad Zahidi Bin Ismail**

Customer Signature **Technician Signature**