Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**87838**
Area		**Date**	**2022-06-02**
Periodic Task		**Time In**	**09:10**
		Time Out	**10:00**

TYPE OF JOB

☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE

☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☑ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			


OPERATIONS

☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding, Abate, Roban baiting for rodents

Location

☑ Presbyterian High School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding carried out to surrounding perimeter drains for control of mosquito breeding, abate granules applied to drains with stagnant water for deterrence purposes.
Roban baits for rodents placed at strategic locations around parade square garden areas for control of rodent activities.
Strongly recommend to clear unused/old flower pots at the back of ISH building.Potential breeding grounds for mosquitoes,and to also flush drain at same location of leaves causing water stagnation.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature

Technician Signature

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**90749**
Area		**Date**	**2022-06-06**
Periodic Task		**Time In**	**08:50**
		Time Out	**09:30**

TYPE OF JOB

☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE

☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			




OPERATIONS

☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding, Abate

Location

☑ Presbyterian High School

Images

			
Notes:	Notes:	Notes:	

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding and Abate granules applied to all service and perimeter drains,including internal garden areas drains for control of mosquito breeding.
No signs of active termites detected during time of inspection.
Do take note of poorly positioned unused ladder behind chapel area,potential water collecting area.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**93564**
Area		**Date**	**2022-06-09**
Periodic Task		**Time In**	**08:45**
		Time Out	**09:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Presbyterian High School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Service Report Presbyterian High School**	**Service Sheet No.**	**96387**
Area		**Date**	**2022-06-13**
Periodic Task		**Time In**	**08:25**
		Time Out	**08:55**

TYPE OF JOB			
☑ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location
☑ Presbyterian High School

Images

Remarks **Carried out for Treatment and Inspection at the above mentioned. Treatment was done at the surrounding perimeter drain of the school. no mosquitoes activity were to be found during the inspection and treatment.**

Name Of Technician **Abdullah Bin Md Kassim**

Customer Signature **Technician Signature**

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**98486**
Area		**Date**	**2022-06-16**
Periodic Task		**Time In**	**08:00**
		Time Out	**08:40**


TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☑ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Presbyterian High School

Images

			
Notes:	Notes:	Notes:	

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
Advised OM to remove ladder placed in open nearby Gate A due to water collection..

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**100612**
Area		**Date**	**2022-06-20**
Periodic Task		**Time In**	**08:05**
		Time Out	**08:50**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Presbyterian High School

Images

Remarks **Inspection carried out to the above mentioned location.**
Due to rain,abate granules applied to all internal areas service drains and canteen floor traps for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**102708**
Area		**Date**	**2022-06-23**
Periodic Task		**Time In**	**08:00**
		Time Out	**08:40**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larvaciding

Location
☑ Presbyterian High School

Images

Remarks **Inspection carried out to the above mentioned location.**
Larvaciding applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature **Technician Signature**



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**103825**
Area		**Date**	**2022-06-27**
Periodic Task		**Time In**	**08:00**
		Time Out	**08:45**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☑ Spot Treatment	☐ Other Control Operation

Location
☑ Presbyterian High School

Images

Remarks **Inspection carried out to the above mentioned location.**
Search and destroy carried today for potential breeding areas..Housekeeping in order..No potential breeding areas found during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R Presbyterian High School**	**Service Sheet No.**	**104935**
Area		**Date**	**2022-06-30**
Periodic Task		**Time In**	**14:35**
		Time Out	**15:15**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Abate

Location
☑ Presbyterian High School

Images

Remarks **Inspection carried out to the above mentioned location.**
Abate granules applied to all service and perimeter drains for prevention of mosquito breeding.
No signs of active termites detected during time of inspection.

Name Of Technician **Faizad Bin Shamsudin**

Customer Signature

Technician Signature

