PRELIMINARY INSPECTION FOR NAVAL BASE PRIMARY SCHOOL – INCLUDING MOE KINDERGARTEN (MK) & KINDERGARTEN CARE (KCARE)

7 Yishun Avenue 4,
Singapore 769028

(Preliminary Inspection Report)

Date: 17th December 2021

Time In: 11.30am Time Out: 12.10pm


Service Report Series Number: 69430

Preliminary Inspection

An inspection was conducted on the 17th December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Surrounding sports complex









Location: Surrounding sports complex





Findings & Recommendation:

1) Spotted chocked drains with accumulation of water and sand particles that might become potential mosquitoes breeding.
2) Kindly maintain well the housekeeping and clean up the sand particulars for preventive measures.

ATL MAINTENANCE PTE LTD
+13 Tagore Industrial Avenue Singapore 787803
Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69430

Name & Contact : NAVAL BASE PRIMARY SCHOOL Date : 17/12/2021

Address : 7, Yishun Ave 4 Time in : 1130 hrs

Time out : 1210 hrs

PRELIMINARY REPORT

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites		☐ Spraying
☑ Cockroaches		☐ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)		☐ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☑ Others Please Specify: ALL Pests.		☐ Others Please Specify:

Remarks: Heavy stagnation of water caused by uneven gradients detected in Sports Complex perimeter drain. Debris & small rocks also causing water stagnation at said location. Potential breeding ground for mosquitoes

Observation / Recommendations : highly recommended to even the gradients & to clear the drain of debris / rocks to enable flow of water

SOR :

☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

NAVAL BASE PRIMARY SCHOOL

Faizal Hamid
Service Attended By

17/12/21
Client's Acknowledgement