PRELIMINARY INSPECTION FOR CHIJ ST NICHOLAS GIRLS SECONDARY SCHOOL

501 Ang Mo Kio Street 13,

Singapore 569405

(Preliminary Inspection Report)

Date: 22nd December 2021

Time In: 10.00am Time Out: 11.00am

Service Report Series Number: 69615

Preliminary Inspection

An inspection was conducted on the 22nd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:


Location: Staircase 17



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Near exit



Findings & Recommendation:

1) Spotted stagnant water that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep good housekeeping on a regular basis for preventive measure.


Location: Near field



Findings & Recommendation:

1) Spotted stagnant water at the canvas that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to keep good housekeeping on a regular basis for preventive measure.

Location: Near field



Findings & Recommendation:

1) Spotted choked drain that filled with soil that might become potential mosquitoes breeding. No active larva was found during the inspection.
2) Advised to clean up the drain on a regular basis for preventive measure.

Location: Near fish pond Agape Blk



Findings & Recommendation:

1) Placed rodenticides bait for monitoring and preventive measures.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803
Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report

S/NO: 69615

Name & Contact : OM MR FOO

Date : 22/12/2021

Address : CHIJ St Nicholas Girls Sec Sch 5 Sch Ang Mo Kio St 13

Time in : 10 00

Time out : 11 00

Preliminary Report for the Month 12/21.

Pest Contracted	Infestation / Service Location	Type Of Treatment
☑ Subterranean Termites	Inspection	☑ Spraying
☑ Cockroaches		☑ Larviciding
☑ Ants (Common / Red)		☐ Fogging
☑ Rodents (Rats / Mice)	Inspection	☑ Baiting
☑ Mosquitoes		☐ Dusting
☑ Bees		☐ Traps
☐ Others Please Specify:	Water Ponding near GYM	☐ Others Please Specify:

Remarks: Water Ponding near staircase 1.T. drain not found w/p at Field Canvas Water Ponding drain not found, w/p new Biology Lab near lift dry WISER 15-20 drain not found, no dead rat Baiting near Fish pond found eggs Bik, No activity found. Inspection at rooftop no activity found.

Observation / Recommendations : Advise to clear all the drain choked to prevent right breeding. and other pest.

SOR : _____

☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

CHIJ ST. NICHOLAS GIRLS' SCHOOL