PRELIMINARY INSPECTION FOR TECK GHEE PRIMARY SCHOOL

1 Ang Mo Kio Street 32,

Singapore 569299

(Preliminary Inspection Report)

Date: 22nd December 2021

Time In: 08.00am Time Out: 09.00am


Service Report Series Number: 69618

Preliminary Inspection

An inspection was conducted on the 22nd December 2021 at the above school. In summary, no major pest issue was found during the time of inspection.

We would like to highlight at the several locations that might become potential pests' habitat and some necessary precautions are needed for preventive measures in the future. Please find the following findings as below:

Location: Perimeter drains near to field area



Findings & Recommendation:

1) Spotted uneven gradient that collect rain water and might become potential mosquitoes breeding.
2) Advised to rectify and level up the gradient in order the water can run smoothly for preventive measures.

Location: Water meter chamber



Findings & Recommendation:

1) Spotted stagnant water that might become potential mosquitoes breeding.
2) Kindly maintain well the drains for preventive measures.

Location: near carpark lot 23



Findings & Recommendation:

1) Spotted stagnant water that might become potential mosquitoes breeding.
2) Kindly maintain well the drains for preventive measures.

Location: Near power grid





Findings & Recommendation:

1) Spotted rodents had eaten the rodenticides bait.
2) To-be-follow up closely during routine service.

ATL MAINTENANCE PTE LTD
413 Tagore Industrial Avenue Singapore 787803
Tel : 6282 2050
Fax : 6841 3182
E-mail: info@atlmaintenance.com.sg

Pest Control Service Report S/NO: 69618

Name & Contact : OM MR LEE Date : 22/12/2021

Address : Teck Ghee Pri schat Time in : 09 00

1, Ang Mo kio st 32 Time out : 09 00

Preliminary Report of the Math 12/2021

Pest Contracted	Infestation / Service Location	Type Of Treatment
☒ Subterranean Termites	Inspection	☒ Spraying
☒ Cockroaches		☒ Larviciding
☒ Ants (Common / Red)		☐ Fogging
☒ Rodents (Rats / Mice)	Inspection	☒ Baiting
☒ Mosquitoes		☐ Dusting
☒ Bees		☐ Traps
☐ Others Please Specify:		☐ Others Please Specify:
	All Posts	

Remarks: Water Ponding near Field G. office drain not level, w/Ponding water meter camber, w/Ponding along near car park lot 23 drain not Level. Inspection o rodent's activity near power grid leaf said, Rodent's Cage has tide. Inspection of rooftop no activity.

Observation / Recommendations : Advise to clear all clocked drain to prevent breeding and other pests.

SOR : ☐ Term Contract ☐ Ad-Hoc / Single Service

☐ Follow-Up Service ☐ Re-Infestation Call Back

Service Attended By

Mr Lee Cheng Koon
Operations Manager