PRIMECH A & P

Area Checklist Report

Checked Date 2023-02-01

Location Block 8

Form Name Block 1 - 8 Male Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**09:03**	**14:14**					**2**
IT8-2-25 Male (04576CF2007481)	Smell	✔	✔					
	Airfreshener	✔	✔					
	Floor	✔	✔					
	Litter Bin	✔	✔					
	Wall	✔	✔					
	Basin	✔	✔					
	Mirror	✔	✔					
	Vanity Top	✔	✔					
	Handsoap / Dispenser	✔	✔					
	Toilet Roll	✔	✔					
	Toilet Bowl	✔	✔					
	Urinal Bowl	✔	✔					
	Hand dryer	✔	✔					
	Partition	✔	✔					
	Ceiling Ventilator / Light	✔	✔					
	Signage	✔	✔					
Time of Check		**10:38**						**1**
IT8-7-29 Male (044D4AD2047481)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						

	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Toilet Bowl	✔						
	Urinal Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						
Time of Check		**10:39**						**1**
IT8-6-27 Male (04CD6CF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Toilet Bowl	✔						
	Urinal Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						