PRIMECH A & P

Area Checklist Report

Checked Date	2023-03-17
Location	Block 27
Form Name	Block 27 Male Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**13:23**	**13:23**					**2**
LB27-3-4 Male (04718BF2007480)	Smell	✔	✔					
	Airfreshener	✔	✔					
	Floor	✔	✔					
	Litter Bin	✔	✔					
	Wall	✔	✔					
	Basin	✔	✔					
	Mirror	✔	✔					
	Vanity Top	✔	✔					
	Handsoap / Dispenser	✔	✔					
	Toilet Roll	✔	✔					
	Toilet Bowl	✔	✔					
	Urinal Bowl	✔	✔					
	Hand dryer	✔	✔					
	Partition	✔	✔					
	Ceiling Ventilator / Light	✔	✔					
	Signage	✔	✔					
Time of Check		**13:23**		**13:23**				**3**
LB27-4-19 Male (04628BF2007480)	Smell	✔		✔				
	Airfreshener	✔		✔				
	Floor	✔		✔				
	Litter Bin	✔		✔				
	Wall	✔		✔				
	Basin	✔		✔				
	Mirror	✔		✔				

	Vanity Top	✔		✔				
	Handsoap / Dispenser	✔		✔				
	Toilet Roll	✔		✔				
	Toilet Bowl	✔		✔				
	Urinal Bowl	✔		✔				
	Hand dryer	✔		✔				
	Partition	✔		✔				
	Ceiling Ventilator / Light	✔		✔				
	Signage	✔		✔				
Time of Check		**13:24**			**13:24**			**4**
LB27-6-12/2 Male (042663F2007480)	Smell	✔			✔			
	Airfreshener	✔			✔			
	Floor	✔			✔			
	Litter Bin	✔			✔			
	Wall	✔			✔			
	Basin	✔			✔			
	Mirror	✔			✔			
	Vanity Top	✔			✔			
	Handsoap / Dispenser	✔			✔			
	Toilet Roll	✔			✔			
	Toilet Bowl	✔			✔			
	Urinal Bowl	✔			✔			
	Hand dryer	✔			✔			
	Partition	✔			✔			
	Ceiling Ventilator / Light	✔			✔			
	Signage	✔			✔			
Time of Check		**13:24**				**13:24**	**13:24**	**6**
LB27-6-20 Male (045E88F2007480)	Smell	✔				✔	✔	
	Airfreshener	✔				✔	✔	
	Floor	✔				✔	✔	
	Litter Bin	✔				✔	✔	

	Wall	✓				✓	✓	
	Basin	✓				✓	✓	
	Mirror	✓				✓	✓	
	Vanity Top	✓				✓	✓	
	Handsoap / Dispenser	✓				✓	✓	
	Toilet Roll	✓				✓	✓	
	Toilet Bowl	✓				✓	✓	
	Urinal Bowl	✓				✓	✓	
	Hand dryer	✓				✓	✓	
	Partition	✓				✓	✓	
	Ceiling Ventilator / Light	✓				✓	✓	
	Signage	✓				✓	✓	