PRIMECH A & P

Area Checklist Report

Checked Date	2022-10-10
Location	Block 42
Form Name	Block 41 to 45 Female Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**10:53**	**15:39**					**2**
42-01-29 (near office) Female (042C8BF2007480)	Smell	✔	✔					
	Airfreshener	✔	✔					
	Floor	✔	✔					
	Litter Bin	✔	✔					
	Wall	✔	✔					
	Basin	✔	✔					
	Mirror	✔	✔					
	Vanity Top	✔	✔					
	Handsoap / Dispenser	✔	✔					
	Toilet Roll	✔	✔					
	Sanitary Bin	✔	✔					
	Toilet Bowl	✔	✔					
	Hand dryer	✔	✔					
	Partition	✔	✔					
	Ceiling Ventilator / Light	✔	✔					
	Signage	✔	✔					
Time of Check		**10:54**		**15:41**				**3**
42-01-37(near cpark) Female (043C8CF2007480)	Smell	✔		✔				
	Airfreshener	✔		✔				
	Floor	✔		✔				
	Litter Bin	✔		✔				
	Wall	✔		✔				
	Basin	✔		✔				
	Mirror	✔		✔				

	Vanity Top	✔		✔				
	Handsoap / Dispenser	✔		✔				
	Toilet Roll	✔		✔				
	Sanitary Bin	✔		✔				
	Toilet Bowl	✔		✔				
	Hand dryer	✔		✔				
	Partition	✔		✔				
	Ceiling Ventilator / Light	✔		✔				
	Signage	✔		✔				