PRIMECH A & P

Area Checklist Report

Checked Date	2024-04-17
Location	Block 9 A
Form Name	Block 9 Female Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**13:52**						**1**
AD9A-1-12 Female (040D8BF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Sanitary Bin	✔						
	Toilet Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						
	1 F	✔						
	10 F	✔						
	11 F	✔						
	12 F	✔						
	2 F	✔						
	4 F	✔						
	5 F	✔						
	6 F	✔						

	7 F	✔						
	8 F	✔						
	9 F	✔						
	3 F	✔						