PRIMECH A & P

Area Checklist Report

Checked Date	2024-12-27
Location	Block 9 A
Form Name	Block 9 Female Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**11:12**	**13:07**					**2**
AD9A-1-12 Female (040D8BF2007480)	Smell	✔	✔					
	Airfreshener	✔	✔					
	Floor	✔	✔					
	Litter Bin	✔	✔					
	Wall	✔	✔					
	Basin	✔	✔					
	Mirror	✔	✔					
	Vanity Top	✔	✔					
	Handsoap / Dispenser	✔	✔					
	Toilet Roll	✔	✔					
	Sanitary Bin	✔	✔					
	Toilet Bowl	✔	✔					
	Hand dryer	✔	✔					
	Partition	✔	✔					
	Ceiling Ventilator / Light	✔	✔					
	Signage	✔	✔					
	1 F	✔	✔					
	10 F	✔	✔					
	11 F	✔	✔					
	12 F	✔	✔					
	2 F	✔	✔					
	4 F	✔	✔					
	5 F	✔	✔					
	6 F	✔	✔					

	7 F	✔	✔					
	8 F	✔	✔					
	9 F	✔	✔					
	3 F	✔	✔					