PRIMECH A & P

Area Checklist Report

Checked Date	2022-09-13
Location	Block 9
Form Name	Block 9 Female Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**17:27**						**1**
AD9-1-67 Female (043988F2007480)	Smell	✔						
Time of Check		**17:34**						**1**
AD9-5-50 Female (04496CF2007481)	Smell	✔						
Time of Check		**17:42**						**1**
AD9-6-44/3 Female (047B8FF2007481)	Floor	✔						
Time of Check		**17:45**						**1**
AD9-7-39 Female (043B65F2007481)	Smell	✔						
Time of Check		**17:49**						**1**
AD9-6-14 Female (041E88F2007480)	Floor	✔						
Time of Check		**17:53**						**1**
AD9-7-13 Female (041A8AF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Sanitary Bin	✔						
	Toilet Bowl	✔						
	Hand dryer	✔						
	Partition	✔						

	Ceiling Ventilator / Light	✔						
	Signage	✔						
Time of Check		**17:55**						**1**
AD9-5-14/3 Female (04416CF2007481)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Sanitary Bin	✔						
	Toilet Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						