PRIMECH A & P

Area Checklist Report

Checked Date	2022-09-13
Location	Block 9
Form Name	Block 9 Male Toilet Checklist

Check Area Name	Check Element Name	Check 1	Check 2	Check 3	Check 4	Check 5	Check 6	Total Checks Done
Time of Check		**17:33**						**1**
AD9-5-49 Male (041464F2007480)	Floor	✔						
Time of Check		**17:37**						**1**
AD9-1-66 Male (043B66F2007481)	Smell	✔						
Time of Check		**17:44**						**1**
AD9-6-43 Male (044B63F2007480)	Litter Bin	✔						
Time of Check		**17:46**						**1**
AD9-7-38 Male (043F8BF2007480)	Litter Bin	✔						
Time of Check		**17:50**						**1**
AD9-6-13 Male (047C6CF2007481)	Litter Bin	✔						
Time of Check		**17:54**						**1**
AD9-7-12 Male (044B8BF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Toilet Bowl	✔						
	Urinal Bowl	✔						
	Hand dryer	✔						
	Partition	✔						

	Ceiling Ventilator / Light	✔						
	Signage	✔						
Time of Check		**17:56**						**1**
AD9-5-13/3 Male (04298AF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Toilet Bowl	✔						
	Urinal Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						
Time of Check		**17:57**						**1**
AD9-4-1/3 Male (048C8BF2007480)	Smell	✔						
	Airfreshener	✔						
	Floor	✔						
	Litter Bin	✔						
	Wall	✔						
	Basin	✔						
	Mirror	✔						
	Vanity Top	✔						
	Handsoap / Dispenser	✔						
	Toilet Roll	✔						
	Toilet Bowl	✔						

	Urinal Bowl	✔						
	Hand dryer	✔						
	Partition	✔						
	Ceiling Ventilator / Light	✔						
	Signage	✔						