


CHYE THIAM MAINTENANCE

ACTIVITY REPORT: Feedback	
Start Time: 2023-06-27 00:34:47	End Time: 2023-06-27 04:44:24
Expressway: AYE	Details: Assets Cleaning 0-26KM BD
Additional Info :	Crew Deployed :
	Supervisor : NIGHT SUP


Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				




Description	

Location	Location Map	Before	During	After
				


Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				




Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				


Description	

Location	Location Map	Before	During	After
				


Description	

Location	Location Map	Before	During	After
				


Description	

Location	Location Map	Before	During	After
				






Description	

Location	Location Map	Before	During	After
				




Description	

Location	Location Map	Before	During	After
				


Description	

Location	Location Map	Before	During	After
				



Description	

Location	Location Map	Before	During	After
				




Description	

Location	Location Map	Before	During	After
				

Description	

Location	Location Map	Before	During	After
				

Description	

Location	Location Map	Before	During	After
				

Task ID: 366