ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/,R WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**291999**
Area		**Date**	**2024-03-04**
Periodic Task		**Time In**	**09:25**
		Time Out	**10:10**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **To execute inspection search and destroy mosquitoes and sub termites in the school area. No pest was found.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



Pest Control Service Report Summary

Messr	**WELLNGTON PRIMARY SCHOOL S/R**	**Service Sheet No.**	**293031**
Area		**Date**	**2024-03-07**
Periodic Task		**Time In**	**07:55**
		Time Out	**09:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Wellington Primary School

Images

Remarks **Inspection for termites and mosquitoes at surrounding areas. No mosquitoes or termites activity found at time of inspection. Larviciding and search and destroy treatment done for prevention against mosquitoes.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**294043**
Area		**Date**	**2024-03-11**
Periodic Task		**Time In**	**08:08**
		Time Out	**09:10**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection & against all pest at common area compound area p/drains drainage gully traps garden area bin ctr roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**295104**
Area		**Date**	**2024-03-14**
Periodic Task		**Time In**	**13:01**
		Time Out	**14:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection search and destroyed at common area compound area p/drains drainage gully traps garden area bin ctr roof and found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**296096**
Area		**Date**	**2024-03-18**
Periodic Task		**Time In**	**08:35**
		Time Out	**09:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection search & destroyed at common area compound area p/drains drainage gully traps garden area bin ctr roof and found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLNGTON PRIMARY SCHOOLS S/R**	**Service Sheet No.**	**297133**
Area		**Date**	**2024-03-21**
Periodic Task		**Time In**	**07:29**
		Time Out	**08:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Wellington Primary School

Images

Remarks **Inspection for termites and mosquitoes at surrounding areas. No mosquitoes or termites activity found at time of inspection. Larviciding and search and destroy treatment done for prevention against mosquitoes.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature

S

ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**298158**
Area		**Date**	**2024-03-25**
Periodic Task		**Time In**	**08:35**
		Time Out	**09:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection & against all pest at common area compound area p/drains drainage gully traps garden area bin ctr roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**298735**
Area		**Date**	**2024-03-27**
Periodic Task		**Time In**	**08:40**
		Time Out	**09:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection search & destroyed at common area compound area p/drains drainage gully traps garden area playground area roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature

