ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**180974**
Area		**Date**	**2023-03-03**
Periodic Task		**Time In**	**13:50**
		Time Out	**14:33**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☑ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☑ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation SnD / Gp

Location
☑ Northoaks Primary School

Images

Remarks **Carried out general pest inspection / search & destroy at the above mention. Search & Destroy was done at the surrounding internal area of the school. Follow Up general pest inspection at ISH, Multie Purpose Hall & Music Room for termites. No sign of active termites were to be found.**
At the point of inspection / service no pest active pest were to be found.

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**182053**
Area		**Date**	**2023-03-07**
Periodic Task		**Time In**	**11:00**
		Time Out	**11:51**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Larviciding

Location
☑ Northoaks Primary School

Images

Remarks **Carried out inspection & larviciding at the above mention. Larviciding was done at the surrounding area of the school. At the point of larviciding no mosquitoes breeding were to be found.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**183149**
Area		**Date**	**2023-03-10**
Periodic Task		**Time In**	**10:48**
		Time Out	**11:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation SnD / Gp

Location
☑ Northoaks Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out general pest inspection / search & destroy at the above mention. Search & Destroy was done at the surrounding area of the school. Follow Up General Pest inspection of rodent activity at Block D Eco Garden. Detect x02 active burrow & baiting was place at the activity area. At the point of service no pest activity / active pest were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**184230**
Area		**Date**	**2023-03-14**
Periodic Task		**Time In**	**11:09**
		Time Out	**11:50**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation SnD

Location
☑ Northoaks Primary School

Images



Notes:



Notes:

Remarks **Carried out search & destroy at the above mention. Search & Destroy was done at the surrounding area of the school. Detect discarded item outside the school fencing . Advice to clear ASAP to prevent mosquitoes activity. At the point of search & destroy no mosquitoes breeding were to be found.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**185298**
Area		**Date**	**2023-03-17**
Periodic Task		**Time In**	**10:58**
		Time Out	**11:43**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation SnD

Location

☑ Northoaks Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out inspection / search & destroy at the above mention. Search & Destroy was done at the surrounding area of the school. At the point of inspection / search & destroy we detect potential area for mosquitoes breeding outside the school fencing. Advice to clear the discarded item to prevent mosquitoes breeding.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR - Northoaks Primary School**	**Service Sheet No.**	**186382**
Area		**Date**	**2023-03-21**
Periodic Task		**Time In**	**11:05**
		Time Out	**11:45**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Lavarciding

Location

☑ Northoaks Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out inspection and treatment for Lavarciding @ entire school. No sign of s/termite activity & no mosq breeding was observed during the time of inspection.Potential MOSQ breeding outside school fencing at behind MK blk. Informed OM. Due to after rain. Dry leave was found almost all the drain.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	



Pest Control Service Report Summary

Messr	**SR - Northoaks Primary School**	**Service Sheet No.**	**187458**
Area		**Date**	**2023-03-24**
Periodic Task		**Time In**	**10:20**
		Time Out	**11:05**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D / GP

Location
☑ Northoaks Primary School

Images

Remarks **Carried out inspection, search & destroy for all pest @ entire school. No sign of s/termite activity & no mosq breeding was observed during the time of inspection.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**SR - Northoaks Primary School**	**Service Sheet No.**	**188531**
Area		**Date**	**2023-03-28**
Periodic Task		**Time In**	**10:50**
		Time Out	**11:40**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation S&D

Location
☑ Northoaks Primary School

Images

Remarks **Carried out inspection, search & destroy @ entire school. No sign of s/termite activity & no mosq breeding was observed during the time of inspection.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**Sr Northoaks Pri Sch**	**Service Sheet No.**	**189590**
Area		**Date**	**2023-03-31**
Periodic Task		**Time In**	**10:20**
		Time Out	**11:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation SnD

Location
☑ Northoaks Primary School

Images

Remarks **Carried out search & destroy at the above mention. Search & Destroy was done at the surrounding area of the school.**
At the point of search & destroy no mosquitoes breeding were to be found.

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature

