Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**318773**
Area		**Date**	**2024-06-03**
Periodic Task		**Time In**	**08:25**
		Time Out	**09:15**

TYPE OF JOB

☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE

☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS

☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location

☑ Wellington Primary School

Images



Notes:



Notes:

Remarks **Carried out inspection & against all pest at common area compound area perimeter drains drainage gully traps roof bin ctr & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**319849**
Area		**Date**	**2024-06-06**
Periodic Task		**Time In**	**08:25**
		Time Out	**09:25**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **To execute inspection search and destroy of mosquitoes and sub termites in the school area.**
No pest breeding was detected.

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



Pest Control Service Report Summary

Messr	**S/R WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**320846**
Area		**Date**	**2024-06-10**
Periodic Task		**Time In**	**08:25**
		Time Out	**09:10**

TYPE OF JOB

☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE

☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS

☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location

☑ Wellington Primary School

Images

Remarks **To execute inspection search and destroy of mosquitoes and sub termites in the school area.**
No pest breeding was detected.

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**S/R WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**321883**
Area		**Date**	**2024-06-13**
Periodic Task		**Time In**	**08:20**
		Time Out	**09:05**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Wellington Primary School

Images

Remarks **To execute inspection search and destroy of mosquitoes larvaciding sub termites in the school area. No pest breeding was detected.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**322940**
Area		**Date**	**2024-06-18**
Periodic Task		**Time In**	**12:10**
		Time Out	**13:10**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection & against all pest at common area compound area perimeter drains drainage gully traps bin ctr garden area roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**323934**
Area		**Date**	**2024-06-20**
Periodic Task		**Time In**	**08:15**
		Time Out	**09:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection search & destroyed at common area compound area perimeter drains drainage gully traps bin ctr garden area roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**324967**
Area		**Date**	**2024-06-24**
Periodic Task		**Time In**	**08:10**
		Time Out	**09:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Wellington Primary School

Images

Remarks **Carried out inspection search & destroyed at common perimeter drains drainage gully traps bin ctr garden area roof & found no sign of activities.**

Name Of Customer

Customer Signature

Name Of Technician **Sahron Bin Ahmad**

Technician Signature



Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL.**	**Service Sheet No.**	**327102**
Area		**Date**	**2024-06-25**
Periodic Task		**Time In**	**13:50**
		Time Out	**14:20**

TYPE OF JOB			
☐ SCHEDULE	☑ SERVICE CALL	☐ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☐ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☑ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☐ Mosquitoes
☐ Rodent	☐ Snake	☐ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☑ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☐ Other Control Operation

Location

☑ Wellington Primary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried out inspection at level 2 classroom 1D cabinet & found drywood termites & treatmentWR/031767/2406/0014**

Name Of Customer **Om Kenny** **Name Of Technician** **Sahron Bin Ahmad**

Customer Signature **Technician Signature**





Pest Control Service Report Summary

Messr	**WELLINGTON PRIMARY SCHOOL**	**Service Sheet No.**	**326010**
Area		**Date**	**2024-06-27**
Periodic Task		**Time In**	**08:20**
		Time Out	**09:15**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Wellington Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out inspection & larviciding treatment at common area compound area perimeter drains drainage gully traps bin ctr garden area roof & found no sign of activities.*Feedback from Om Raju wood borers at cleaner store room & treatment done.**

Name Of Customer		**Name Of Technician**	**Sahron Bin Ahmad**
Customer Signature		**Technician Signature**	

