ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**309573**
Area		**Date**	**2024-05-03**
Periodic Task		**Time In**	**13:15**
		Time Out	**14:45**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No termite or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**310591**
Area		**Date**	**2024-05-07**
Periodic Task		**Time In**	**09:40**
		Time Out	**10:45**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No pest or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**311630**
Area		**Date**	**2024-05-10**
Periodic Task		**Time In**	**12:00**
		Time Out	**12:50**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No pest or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**312658**
Area		**Date**	**2024-05-14**
Periodic Task		**Time In**	**11:25**
		Time Out	**12:23**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No termite or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**313697**
Area		**Date**	**2024-05-17**
Periodic Task		**Time In**	**11:45**
		Time Out	**12:50**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No termite or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature

Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**314750**
Area		**Date**	**2024-05-21**
Periodic Task		**Time In**	**10:35**
		Time Out	**11:50**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No pest or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



ATL MAINTENANCE PTE LTD

SWIPETASK

Ministry of Education SINGAPORE

Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**315775**
Area		**Date**	**2024-05-24**
Periodic Task		**Time In**	**11:50**
		Time Out	**12:35**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No pest or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**316803**
Area		**Date**	**2024-05-28**
Periodic Task		**Time In**	**11:00**
		Time Out	**12:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy

Location
☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done at the above mentioned location.No termite or mosquito activity found at the time of service.**

Name Of Customer

Customer Signature

Name Of Technician **Rosli Bin Sinwan**

Technician Signature



Pest Control Service Report Summary

Messr	**WRPS**	**Service Sheet No.**	**317829**
Area		**Date**	**2024-05-31**
Periodic Task		**Time In**	**11:40**
		Time Out	**12:40**

TYPE OF JOB

☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE

☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS

☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location

☑ Woodlands Ring Primary School

Images

Remarks **Inspection and treatment done.No termite or mosquito activity found at the time of service.**

Name Of Customer		**Name Of Technician**	**Rosli Bin Sinwan**
Customer Signature		**Technician Signature**	