Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**256318**
Area		**Date**	**2023-11-02**
Periodic Task		**Time In**	**10:20**
		Time Out	**11:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☑ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☑ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	Notes:
			
Notes:	Notes:		

Remarks	**Carried out all general pest inspection / search & destroy at the above mention.All general pest inspection / search & destroy was done at the surrounding area of the school.At the point of all general pest inspection / search & destroy follow up through final check of drywood termites at MPH school hall. No sign of active drywood termites were to be found. School Canteen Corridor behind school piano caught 01x shrew. No sign of other pest activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**257327**
Area		**Date**	**2023-11-06**
Periodic Task		**Time In**	**10:50**
		Time Out	**11:33**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Trapping

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	Notes:

Remarks **Carried our search & destroy for mosquitoes control &s/termites at the above mention.Search & Destroy was done at the surrounding area of the school, & replace x01 glueboard at school canteen corridor behind piano. School remove dead rodent on the glueboard themselve. No photo given.At the point of search & destroy no sign of mosquitoes & s/termites activity were to be found.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**258333**
Area		**Date**	**2023-11-09**
Periodic Task		**Time In**	**11:32**
		Time Out	**12:10**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation search & destroy

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	Notes:
			
Notes:	Notes:		

Remarks	**Carried out all general pest / preventive measurement at the above mention.All General Pest Inspection / Preventive measurement was done at the surrounding area of the schoolAt the point of all general pest inspection / preventive measurement no sign of pest activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**259357**
Area		**Date**	**2023-11-14**
Periodic Task		**Time In**	**11:03**
		Time Out	**11:40**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation search & destroy

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	Notes:
			
Notes:	Notes:		

Remarks	**Carried out larviciding for mosquitoes control & s/termites at the above mention.Larviciding was done at the surrounding area of the school for preventing of mosquitoes activity.At the point of larviciding no sign of mosquitoes & s/termites activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	



Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**260345**
Area		**Date**	**2023-11-16**
Periodic Task		**Time In**	**11:13**
		Time Out	**11:55**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding, Trapping

Location
☑ Admiralty Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out all general pest / search & destroy at the above mention.All general pest inspection / search & destroy was done at the surrounding area of the school. Follow up rodent inspection & other pest activity. Caught x01 rodent at ISH Staircase Landing Lvl 1 staircase 12 . Found ants activity at ISH sport tower outside dry riser room. Gassing done on the activity area. No sign of ants nest were to be found.At the point of all general pest inspection / search & destroy no sign of pest activity were to be found.*Remark* - Replace 01x glueboard at the activity area.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**261351**
Area		**Date**	**2023-11-20**
Periodic Task		**Time In**	**11:21**
		Time Out	**12:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation search & destroy

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	

Remarks **Carried out search & destroy at the above mention.Search & Destroy was done at the surrounding area of the school & school rooftop for preventing of mosquitoes activity.At the point of search & destroy no sign of mosquitoes & s/termites activity were to be found.**

Name Of Customer

Customer Signature

Name Of Technician **Jannatul Firdaus Bin Awang**

Technician Signature



Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**262356**
Area		**Date**	**2023-11-23**
Periodic Task		**Time In**	**11:13**
		Time Out	**12:00**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation search & destroy

Location
☑ Admiralty Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out all general pest / search & destroy at the above mention.All General Pest Inspection / Search & Destroy was done at the surrounding area of the school & rodent inspection.No sign of bitten on rodent baiting & no sign of rodent were caught on the glueboard.At the point of all general pest inspection / search & destroy no sign of pest activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**263372**
Area		**Date**	**2023-11-27**
Periodic Task		**Time In**	**10:52**
		Time Out	**11:30**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☐ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation search & destroy

Location
☑ Admiralty Primary School

Images



Notes:



Notes:



Notes:



Notes:



Notes:



Notes:

Remarks	**Carried out search & destroy at the above mention.Search & Destroy was done at the surrounding area of the school for preventing of mosquitoes activity.At the point of search & destroy no sign of mosquitoes & s/termites activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	

Pest Control Service Report Summary

Messr	**SR ADMIRALTY PRI SCH**	**Service Sheet No.**	**264357**
Area		**Date**	**2023-11-30**
Periodic Task		**Time In**	**11:10**
		Time Out	**11:55**

TYPE OF JOB			
☐ SCHEDULE	☐ SERVICE CALL	☑ ROUTINE WORKS	☐ FOLLOW-UP
☐ TIME SERVICE	☐ OTHERS		

PEST TYPE			
☑ All Pest(Survey)	☐ Ants	☐ Bats	☐ Bees
☐ Beetles	☐ Birds	☐ Cats	☐ Cockroaches
☐ Dogs	☐ Drywood Termites	☐ Fleas	☐ Flies
☐ Hornet	☐ Lice	☐ Mites	☑ Mosquitoes
☑ Rodent	☐ Snake	☑ Subterranean Termites	☐ Wasps
☐ Other Pest(add name)			

OPERATIONS			
☐ ULV	☐ Fogging	☐ Gassing	☐ Handspray
☐ Misting	☐ Soil Treatment	☐ Spot Treatment	☑ Other Control Operation Search & Destroy, Larviciding

Location
☑ Admiralty Primary School

Images

			
Notes:	Notes:	Notes:	Notes:
			
Notes:	Notes:		

Remarks	**Carried out larviciding at the above mention.Larviciding was done at the surrounding area of the school.Inform from the school cleaner that they disposed dead rodent caught on the rodent glueboard behind school piano canteen corridor. No photo were taken from them.At the point of larviciding no sign of mosquitoes & s/termites activity were to be found.**

Name Of Customer		**Name Of Technician**	**Jannatul Firdaus Bin Awang**
Customer Signature		**Technician Signature**	