PRIMECH SERVICES & ENGRG PTE LTD
21 BUKIT BATOK CRESCENT , 03 - 79 WCEGA TOWER,
Singapore, 658065
sam@ifsc.sg
62861868

NYP Monthly Inspection Report 2016

16 Nov 2016

Zone Selection & Inspector Name

Zone / Location:	BLK H / J / K
Inspected By:	Chris

Entrance & Lobby

1) Door Surface / Frames / Closer	4	
2) Floor / Skirting	5	
3) Wall / Partition	4	
4) Ceilling / Partition	4	
5) Glass / Window	4	
6) Power Point / Signage	5	
7) Fire Hosereel / Extingusher	5	
Sub -Total		31.00

Corridor

1) Door Surface / Frames	3	
2) Floor / Skirting	5	
3) Wall / Partition	5	
4) Ceiling / Aircon Diffuser / Light Diffuser	4	
5) Glass / Window	4	
6) Fitting / Furniture	5	
7) Power Point / Signage	5	
8) Fire Hosereel / Extinguisher	5	
Sub-Total		36.00

Staircase & Landing

1) Door Surface / Frames	5	
2) Floor	5	
3) Wall	3	
4) Ceiling	4	
5) Steps	4	
6) Railing	5	
7) Signage	4	
Sub-Total		30.00
% Total Score Achieved		88.18

Submitted by: Supervisor @ 01:47:42 16 Nov 2016 Version: 17
Submission ID: 613964
Environment friendly, paperless solution by www.formitize.com

Submitted By:	Chris
Signature	

Submitted by: Supervisor @ 01:47:42 16 Nov 2016 Version: 17
Submission ID: 613964
Environment friendly, paperless solution by www.formitize.com